

Plug-in CTs

- No leads supplied with these CTs (RJ45 connection cable)
- For technical data see page 1.65.

Description	Cat ref.
125A Frame Size 60A 3 Phase CT	EC1260CT
125A Frame Size 100A 3 Phase CT	EC12100CT
125A Frame Size 125A 3 Phase CT	EC12125CT
125A Frame Size 160A 3 Phase CT	EC12160CT
250A Frame Size 60A 3 Phase CT	EC2560CT
250A Frame Size 100A 3 Phase CT	EC25100CT
250A Frame Size 125A 3 Phase CT	EC25125CT
250A Frame Size 160A 3 Phase CT	EC25160CT
250A Frame Size 200A 3 Phase CT	EC25200CT
250A Frame Size 250A 3 Phase CT	EC25250CT
400A Frame Size 250A 3 Phase CT	EC40250CT
400A Frame Size 400A 3 Phase CT	EC40400CT
400A Frame Size 630A 3 Phase CT	EC40630CT
800A Frame Size 800A 3 Phase CT	EC80800CT



EC1260CT

Commercial
Distribution

Meter Cables

Description	Cat ref.
Meter Voltage Supply Cable - PVC	
1m - Voltage Supply Cable with Fuse Carrier (For JF Meter Enclosures)	JF130VMF
1m - Voltage Supply Cable with Fuse Carrier (For JN Meter Enclosures)	JN130VMF
0.30m - Hi Flex Voltage Supply Cable	PGMF300
0.50m - Hi Flex Voltage Supply Cable	PGMF500
1.00m - Hi Flex Voltage Supply Cable	PGMF1000
1.30m - Hi Flex Voltage Supply Cable	PGMF1300
2.00m - Hi Flex Voltage Supply Cable	PGMF2000
3.00m - Hi Flex Voltage Supply Cable	PGMF3000



JFA03



JFA03

Meter to Meter Supply Cable - PVC

0.15m - Hi Flex Meter to Meter Supply Cable	PGMFT150
0.30m - Hi Flex Meter to Meter Supply Cable	PGMFT300
0.50m - Hi Flex Meter to Meter Supply Cable	PGMFT500
1.00m - Hi Flex Meter to Meter Supply Cable	PGMFT1000
1.30m - Hi Flex Meter to Meter Supply Cable	PGMFT1300
2.00m - Hi Flex Meter to Meter Supply Cable	PGMFT2000
3.00m - Hi Flex Meter to Meter Supply Cable	PGMFT3000

RJ45 Connection Cable

Description	Cat ref.
0.30m - RJ45 Connector Cable 67 7003	PGRJ300
0.50m - RJ45 Connector Cable 67 L7005 LSZH	PGRJ500
1.00m - RJ45 Connector Cable 67 L7005 LSZH	PGRJ1000
1.50m - RJ45 Connector Cable 67 L7005 LSZH	PGRJ1500
2.00m - RJ45 Connector Cable 67 L7005 LSZH	PGRJ2000
3.00m - RJ45 Connector Cable 67 L7005 LSZH	PGRJ23000



PGRJ1000

Accessories

- Supply voltage connector plugs are for making up your own power cable looms.

Description	Cat ref.
Supply Voltage Connector Plugs Voltage IN (Male) Connector	PG9523MALE
Supply Voltage Connector Plugs Voltage OUT (Female) connector	PG9522FEMALE
CT Output and RJ45 Lead Tester	JFT03



JFT03



PG9522FEMALE